



Inventory Health / Status - Infiniti Marin -

From: 9/5/2019

To: 9/5/2019

Found vehicles

Order	Stock #	Notes
No vehicles.		

Not Found / No Status

Stock #	Date
I01255	8/6/19 6:23PM
I01257	8/9/19 10:22PM
I01259	8/22/19 6:23PM
I01261	8/23/19 6:22PM
I01262	9/4/19 6:21PM
I01263	9/4/19 6:21PM

Vehicles w/o data (Not in feed)

Stock #	Date
I18029	5/17/19 1:19PM
I18053R	5/30/19 10:19PM
I18208R	8/6/19 6:23PM

Not Ready for Photos - Most Recent Status

Stock #	Status
025015	Off Site (9/3/19 2:22PM)
I01022	Dirty (8/8/19 2:46PM)
I01027A	Service (9/5/19 2:30PM)
I01078A	Service (9/3/19 2:22PM)
I01233	Dirty (8/8/19 2:46PM)
I01250	Service (7/25/19 1:36PM)
I01251	Service (7/25/19 1:50PM)
I01252	Dirty (8/1/19 2:15PM)
I17292	Service (9/5/19 2:23PM)
I17294B	Service (9/5/19 2:23PM)

I17948S	Service (9/5/19 2:15PM)
I18098A	Service (9/5/19 2:19PM)
I18105	Service (9/3/19 2:22PM)
I18129	Awaiting Detail (9/5/19 12:24PM)
I18174A	Service (9/5/19 2:17PM)
I18175L	In transit (9/5/19 2:36PM)
I18181B	Service (9/3/19 2:22PM)
I18188A	Service (9/3/19 2:22PM)
I18204R	Service (9/3/19 2:23PM)
I18208R	Key Missing (9/3/19 2:23PM)
I18222K	Service (9/5/19 2:25PM)
I18228	Service (9/3/19 2:23PM)
I18229	Service (9/5/19 2:17PM)
I18232L	Service (9/5/19 2:32PM)
I18233A	Service (9/5/19 2:21PM)
I18235	In transit (9/3/19 2:23PM)
I18236	Service (9/5/19 2:27PM)
I18238R	Dirty (8/29/19 11:21AM)
I18244	Service (9/5/19 2:25PM)
I18246A	Service (9/5/19 2:14PM)
I18247R	Service (9/3/19 2:25PM)
I18248R	Dirty (9/3/19 2:25PM)
I18249R	Service (9/5/19 2:31PM)
I18250	Service (9/5/19 2:24PM)
I18251	Dirty (9/3/19 2:25PM)
I18252R	Dirty (9/3/19 2:25PM)
I18253A	Service (9/3/19 2:25PM)
I18256	In transit (9/5/19 2:36PM)
I18257A	Service (9/5/19 2:22PM)
I18259R	In transit (9/5/19 2:36PM)
I18260R	In transit (9/5/19 2:36PM)
I18261R	In transit (9/5/19 2:36PM)
I18262R	In transit (9/5/19 2:36PM)
I18263R	In transit (9/5/19 2:36PM)
I18264	In transit (9/5/19 2:36PM)
I18265	In transit (9/5/19 2:36PM)
I18270B	In transit (9/5/19 2:36PM)
I18271	In transit (9/5/19 2:36PM)
I18273	In transit (9/5/19 2:36PM)
I18274	In transit (9/5/19 2:36PM)
I18276	In transit (9/5/19 2:36PM)
I18287R	In transit (9/5/19 2:36PM)
I18288R	In transit (9/5/19 2:36PM)
I18289R	In transit (9/5/19 2:36PM)
IN0055B	Dirty (9/5/19 2:15PM)

Photographed vehicles

Stock #	Photos	Date
I01266	14	9/5/19 7:50PM
I01268	14	9/5/19 7:50PM
I01269	14	9/5/19 7:50PM
I18098A	7	9/5/19 2:20PM
I18129	7	9/5/19 12:23PM
I18138R	36	9/5/19 1:15PM
I18195	36	9/5/19 1:33PM
I18230R	36	9/5/19 1:46PM
I18232L	7	9/5/19 2:32PM
I18233A	7	9/5/19 2:21PM
I18244	7	9/5/19 2:25PM
I18249R	7	9/5/19 2:31PM
I18250	7	9/5/19 2:24PM
I18257A	7	9/5/19 2:23PM
I18278	36	9/5/19 2:02PM

©Pro-MotionPix