



Inventory Health / Status - San Leandro Nissan - All ▾

From: 6/5/2019

To: 6/5/2019

Found vehicles

| Order | Stock # | Notes |
|--------------|---------|-------|
| No vehicles. | | |

Not Found / No Status

| Stock # | Date |
|----------|-----------------|
| 386678S | 3/15/19 11:22AM |
| 726157SS | 3/11/19 10:24AM |
| 801619S | 3/11/19 10:24AM |
| KN751460 | 4/23/19 8:24AM |
| KN765039 | 5/30/19 8:25AM |
| KN800615 | 4/23/19 8:24AM |

Vehicles w/o data (Not in feed)

| Stock # | Date |
|----------|-----------------|
| 026879 | 3/14/19 11:40AM |
| 080569 | 3/14/19 11:40AM |
| 241076 | 3/14/19 11:41AM |
| 300375 | 3/14/19 5:28PM |
| 332494 | 3/14/19 11:39AM |
| R188373S | 3/11/19 10:25AM |
| R232991S | 3/11/19 10:24AM |
| T021015S | 5/14/19 8:25AM |
| T544089S | 5/5/19 9:23AM |

Not Ready for Photos - Most Recent Status

| Stock # | Status |
|----------|-------------------------------|
| 502128SS | Lot 2 (5/29/19 5:16PM) |
| 504849S | Lot 2 (5/29/19 5:16PM) |
| 505353S | Lot 2 (5/29/19 5:16PM) |
| 517943S | Key Missing (4/12/19 12:03PM) |

| | |
|----------|--|
| 590625S | OFFSITE - Dead Battery (5/29/19 12:17PM) |
| 740761SS | Dirty (4/12/19 12:03PM) |
| 800758S | off site/not pdi'd (5/29/19 5:16PM) |
| 818998S | off site/not pdi'd (5/29/19 5:16PM) |
| KN134730 | off site/not pdi'd (5/29/19 5:17PM) |
| KN756386 | Off Site / No Key (5/29/19 5:17PM) |
| KN805713 | Key Missing (5/29/19 5:17PM) |
| KN851477 | Key Missing (5/29/19 5:17PM) |
| P057315S | Demo (6/5/19 9:08AM) |
| S1040 | Service (6/5/19 9:07AM) |
| S1042 | Service - On Rack - Apart (6/5/19 9:08AM) |
| S1043 | Service (6/5/19 8:55AM) |
| S1047 | Service - On Rack - Apart (6/5/19 9:08AM) |
| SR1032 | Service (6/5/19 8:56AM) |
| SR1033 | Service - On Rack - Apart (6/5/19 9:08AM) |
| SR1034 | Service (6/5/19 9:00AM) |
| SR1035 | Service - On Rack - Apart (6/5/19 9:08AM) |
| SR1041 | Service (6/5/19 9:03AM) |
| SR1044 | Service (6/5/19 9:02AM) |
| T108202S | Service (6/5/19 9:02AM) |
| T225523S | Service (6/5/19 9:08AM) |
| T269013S | off site/dirty (6/5/19 9:06AM) |
| T339428S | Service (6/5/19 9:08AM) |
| T397114S | Service (6/5/19 9:08AM) |
| T601673S | Service (6/5/19 9:08AM) |
| T621461S | Wholesale - MANAGER ONLY (5/17/19 12:51PM) |
| TA43964S | Service (6/5/19 9:08AM) |

Photographed vehicles

| Stock # | Photos | Date |
|----------|--------|---------------|
| S1037 | 1 | 6/5/19 9:10AM |
| S1037 | 30 | 6/5/19 9:11AM |
| S1038 | 1 | 6/5/19 9:18AM |
| S1038 | 32 | 6/5/19 9:18AM |
| S1039 | 1 | 6/5/19 9:14AM |
| S1039 | 32 | 6/5/19 9:14AM |
| S1040 | 1 | 6/5/19 9:07AM |
| S1043 | 1 | 6/5/19 8:56AM |
| SR1032 | 1 | 6/5/19 8:57AM |
| SR1034 | 1 | 6/5/19 9:01AM |
| SR1036 | 1 | 6/5/19 9:20AM |
| SR1036 | 30 | 6/5/19 9:21AM |
| SR1041 | 1 | 6/5/19 9:05AM |
| SR1044 | 1 | 6/5/19 9:03AM |
| T108202S | 1 | 6/5/19 9:01AM |

©Pro-MotionPix